

General Description

Working under the direction of the Fabricating Supervisor, this position is responsible for operating the plasma cutter, laser cutter, or press to produce parts to specification, ensuring quality and efficiency in the manufacturing process.

Education, Certifications, Licenses, and/or Registrations

A high school diploma or equivalent is preferred.

Experience

Minimum one (1) year general production experience is preferred. Forklift experience is preferred.

Specialized Knowledge and Skills

- Must possess proficient technical knowledge and manual dexterity
- Basic math and reading skills
- Able to read tape measure
- Able to use basic hand and power tools
- Able to follow instructions and retain information
- Willingness to learn
- Physical stamina

Essential Duties

1. Read and follow work instructions and blueprints and established procedures.
2. Collect all material and equipment needed for the assigned process.
3. Communicate with forklift operator for material needs.
4. Communicate with trainer and/or supervisor regarding performance and/or material issues.
5. Select and set up lenses (and other consumables) based on material type and thickness, load programs, and set up machine parameters to ensure optimal performance of the equipment.
6. Understand shield gases used during cutting operations when operating the plasma or laser.
7. Call for quality control when product is ready for inspection.
8. Perform other duties such as grinding, de-burring, cleaning parts, and removing scrap.
9. Use precision measurements to ensure quality of part.
10. Lift materials and final products manually or using a hoist.
11. Accurately report production in the computer system.
12. Provide a great level of attention to detail and focus on given task.
13. Follow all company and safety policies, guidelines, and rules.
14. Follow all quality standards.
15. Meet and/or exceed production goals.
16. Work in a fast-paced environment.
17. Stay focused and on task with minimal supervision.
18. Maintain a clean and organized work area.
19. Maintain regular and reliable attendance.
20. Perform other duties as assigned.

Work Environment

Industrial manufacturing environment. Facility is enclosed, ventilated, and heated but not air conditioned. Safety-toe footwear and safety eyewear are required. Hearing protection is required in designated areas. Gloves and other PPE are provided.

Physical Demands

Spends more than three-quarters (3/4) of the time standing, kneeling/crouching/stooping, using hands, and reaching. Able to lift up to 75 lbs. and occasionally position heavier material with the aid of a lifting device(s). Requires clear vision at close distances for reading blueprints, instructions, and precision measuring instruments.

Schedule

Full time. First shift 5:30 AM – 3:45 PM, Monday through Thursday. Second shift 3:45 PM – 2:00 AM, Monday – Thursday. All training is done on first shift. Overtime may be required.

Please note, this job description is not designed to cover or contain a comprehensive listing of activities, duties, or responsibilities that are required of the employee for this job. Activities, duties, and responsibilities may change at any time with or without notice.

For more information, call 573-642-2246 ext. 224. Or email hr@danuser.com.

Apply Now

If button does not work, copy and paste this URL into your browser window:
<https://www.danuser.com/our-company/careers/application-form>